

Menu

HISTORY FILE MAP for year 2002


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

261.00:13-01:20: 1h 7m 1024bps RT / 2h 14m 512bps PB data and 50m 1024bps RT / 1h 23m 512bps PB data lost  
(260.10:50-13:04) due to high winds at DSS-34, forcing the antenna to go to stow. DSS-24 acquired until  
261.02:22-03:12 S/C passed out of view. DR C101665 refers.  
(260.07:25-08:48)



267.20:11-20:13: 2m Real-time 1024bps data and 12m 512bps playback data lost due to DSS-25 Standard  
(266.22:25-22:37) Control Processor (SCP) problems. DR G101610 refers.